

National Standards for Physical Inspection of Real Estate





Presenters

Nicole Landry

Wesley Cager

Why Change

The purpose of NSPIRE is to reduce regulatory burden and improve HUD oversight by aligning and consolidating the inspection regulations used to evaluate HUD housing across multiple programs.

- □ Prioritizes health, safety, and functional defects over those about appearance.
- □ Alignment of multiple inspection standards.
- □Clearly defined inspection standards and protocols.

The new NSPIRE model prioritizes health, safety, and functional defects over appearance. It implements inspections that better reflect the actual physical conditions of the property and supports the adoption of sound, year-round maintenance practices.

5

The Good, The Bad, and The Ugly

Inspectable Area

- ☐ Inside (I): Inside of HUD housing (or "inside areas") refers to the common areas and building systems that can be generally found within the building interior and are not inside a unit.
- □ Outside (O): Outside of HUD housing (or "outside areas") refers to the building site, building exterior components, and any building systems located outside of the building or unit.
- ☐ Unit (U): A unit (or "dwelling unit") of HUD housing refers to the interior components of an individual unit.

7

Multifamily - Apartments

Outside

- Grounds
- Parking lot
- Playground
- Swimming pool

Inside

- · Community room
- · Workout facility
- Mail Room
- Office
- · Laundry Room
- · Electrical Room

Unit

- Where the tenant lives
- · Porch

Single Family/Duplex

Outside:

- Yard
- Driveway
- Sidewalk

Inside

• Detached Garage/storage room (TT has access)

Unit

· Where the tenant lives

9

Inspection Types

- Initial
- ☐ Annual and Biennial Inspection
- Special Unit Inspection (Quality Control and Compliant)
- Virtual Inspection

NSPIRE vs NSPIRE-V

NSPIRE – This is a specific application of the NSPIRE standards to the Tax Credit HUD Unit/Multifamily and Public Housing. They use a point system vs Pass/Fail for NSPIRE-V.

NSPIRE-V This is a specific application of the NSPIRE standards to the Housing Choice Voucher (HCV) program, also known as Section 8. It was initially referred to as <u>UPCS-V</u> during a demonstration phase, but has evolved into NSPIRE-V. NSPIRE-V replaces the previous HQS standards for HCV inspections.

11

Inspection Results

Pass or Fail



Inspection Correction Timeframes

Low - Pass (with comments)

Moderate: Failed 30 days

Severe: Failed (within 30 days - Per Admin Plan)

Life Threatening (LFT): 24 Hours

13

No Defect

Address and Signage (O & I)






15

Address and Signage (O)

Failed - Address or building ID Code is broken, illegible, or not visible

Repair Time: Up to 30 days



Call-For-AID System (U&I)



- System blocked
- ☐ Pull the cord within 6 inches of the floor
- ☐ System does not function properly
- □ FAILED 24hrs Repair

17

Carbon Monoxide



Inspecting Carbon Monoxide Alarms

CHARLEST STREET, STREE

Carbon Monoxide Alarms (U&I)



- ☐ If the unit or inside has a fuel-burning appliance, fireplace, or attached garage
- ☐ The CO alarm is missing and not installed in the proper location
- ☐ The CO alarm is missing and not installed in the proper location
- Does not produce audio or visual alarm on test
- □ Location Vicinity of the bedrooms/classrooms or in the same room as the fuel-burning item.

FAILED - 24 Hrs.

19

Chimney (U,I & O)



- ☐ Wood-burning chimney incomplete/unsafe
- ☐ Chimney exhibits signs of structural failure
- ☐ FAILED 24 Hrs.

Clothes Dryer Exhausted Ventilation (U&I)

- ☐ The electric dryer exhaust ventilation system has restricted airflow
- ☐ The electric/gas dryer transition duct is detached or missing
- ☐ Exterior vent cover, cap, or a component is missing
- Exterior vent is clogged
- ☐ Dryer transition duct is constructed if unsuitable material (White hose is NOT Allowed)
- ☐ Gas dryer exhaust ventilation system has restricted airflow
- □ FAILED 24 hrs.

21

Dryer Vent

LOW-PASS (BROKEN)



LOW-PASS (MISSING)



Dyer Vent Blocked/Clogged

24 HRS. LFT - FAILED



24 HRS. LFT - FAILED



23

Clothes Dryer Exhausted Ventilation (U&I)





Clothes Dryer Exhausted Ventilation (U&I)





25

Doors (Exterior, Exit or Entry)

- Missing door
- ☐ Does not open or close properly
- ☐ Missing locks (Must have two Locks Keyless deadbolt)
- Peephole, Door window, or window that will allow the tenant to see who is at the front of the door
- ☐ The door is not secured
- ☐ Light coming through the door and frame (Weatherstripping) Size ¼ inch gap or water
- Holes, splits, or cracks penetrated through the door, causing issues with the operation of the door
- $\hfill \square$ Self-closing mechanism is damaged, missing or inoperable







27


Damaged Door





Damaged Door





29

Screen Doors



Doors (Screen Doors)

- •Are not inspectable
- Unless it has SharpEdges or EgressIssues



31

Entry Doors



Doors Inside (U&I)

- ☐ Door must be present (Bedroom and Bathroom Only)
- ☐ Passage does not open
- ☐ No lock requirement except the bathroom
- ☐ Door is secured and works as designed Pass
- □ No holes, splits, or cracks penetrated through the door Pass

33

Broken Bedroom Doors







Doors (Fire Door) – 24 Hr Fail

- ☐ The door labeled is missing or evidence of prior installation
- Does not open and close as designed
- Fire door is propped open/Kickstand
- Must have a label
- ☐ No holes, splits, or cracks penetrated through the door
- Damaged assembly

35

Door (Fire Door)





Door (Fire Door)





37

Fire Doors



Inspecting Fire-Labeled Doors

Fire Door Repair

- Repairs to fire doors must include the manufacturer's documentation
- •If the fire door has 25% or more of surface rust, it will be cited as a Severe Defect

39

Foundation

- Damage to the missing vent (Circulation Vents)
- > Crack > 1/4 x 12"
- ➤ Rod/damaged noted to 12' x 12 x ¾ deep

Main Egresses

- Entry Doors (Exterior Door)
- Bedroom Door
- Bedroom Window (at least one)

41

Egress (U,I&O)

- ☐ Obstructed egress route or opening
- ☐ Bedroom < 4th floor obstructed rescue opening, not a resident item
- ☐ Fire escape obstructed, excluding resident-owned items
- □ An LL-owned permanent window AC unit cannot block an egress.
 □ NOTE: Tenant-owned AC unit CAN block egress
- ☐ FAILED 24 hrs.

Egress (U,I&O)





43

Egress



The AC unit CANNOT Block only the window in a bedroom.

No matter the ownership

Egress

Tenant-owned furniture may block the only window in the bedroom.

Note: We will encourage them to move the item



45

Egress (U,I&O)



Clutter CANNOT block an Entry door.

No matter the ownership


Egress (U,I&O)

LFT – 24 Hrs. Fail Note: If this is the only window in the bedroom



47

Egress



Electrical – Outlet, Switch, exposed wires (U, I & O)

- □ The outlet or switch is damaged such that it is unsafe.
- > Three-pronged outlet is not grounded or wired properly
- ➤ No damaged but doesn't work
- ☐ Exposed electrical conductor/wires
- ☐ Water is currently in contact with an electrical conductor

49

Electrical Outlet (U, I & O)





Electrical Outlet (U, I & O)





51

Electrical Wires (U, I & O)





Electrical Boxed (U, I & O)






53

Wall Mount Light Fixture (O, I, & U)

Missing globe on wall-mounted light (Only)

24 Hour - LFT



Failed



55

Electrical GFCI or AFCI Outlet Breaker

- ☐ GFCI outlet or breaker test or the reset button is inoperable
- ☐GFCI outlet or AFCI breaker test or the reset button is inoperable
- ☐ Unprotected outlet within six feet of a water source UAHR
- ☐ Failed Up to 30 Days

Electrical GFCI Outlets (U, I & O)





57

Is A GFCI Required?





GFCI or AFCI



59

Electrical – Service Panel

- ☐ The electrical service panel is not reasonably accessible
- ☐ The overcurrent protection device is damaged 24 Hrs.
- ☐ The overcurrent protection device is contaminated

Wesley Cager



61

Exit Signs (I & O)



- Missing
- Damaged
- Not Illuminated
- Not installed properly
- ☐ Failed 24 Hrs.

Exit Signs (I & O)





63

Fire Escape (O)





Fire Extinguisher (U, I &O)

- ☐ Fire extinguisher pressure gauge reads over or under-charged
- ☐ The fire extinguisher service tag is missing, illegible, or expired
- ☐ Fire extinguisher is damaged or missing
- ☐ A Disposable Fire Extinguisher over 12 years old

NOTE: A tenant-owned fire extinguisher is not evaluated

☐ Failed - 24 Hrs.

65

Fire Extinguisher (U, I &O)





Missing



Proof of prior installation of a Fire Extinguisher

67

Flammable and Combustible (U,I &O)



- ☐ Within 3' source of ignition; improperly stored chemicals, lawnmower, and other gas devices
- ☐ Away from a furnace or heater
- ☐ Failed 24 hrs.

Garage Door

- ☐ Hole of any size that penetrated through the interior
- Door does not open, close, or remain open or closed
- Failed Up to 30 days


69

Damaged Garage Doors





Guard Rail vs Hand Rail



71

Grab Bar (U& I)

- Missing Grab Bars (previously installed)
- ☐ Not Secured (Any Movement)



Guardrails (U,I &O)

- ☐ The guardrail is missing or not installed
- ☐ Inadequate, missing, damaged, less than 30" high, not secure
- ☐ Failed 24 Hrs.



73

Handrail (U,I &O)





Handrail - (U,I &O)

- ☐ Has four consecutive steps or more
- Not secured
- Other areas where a handrail was required and previously installed (failed)
- □ No signs of prior installation (Low Pass)



75

Not a Defect

Reminder:

Must have four consecutive steps or more.

Do not count the landing.



Handrail Ramps NOTE:

Handicap Ramp:

- The ramp raises 6 inches or runs 6 feet.
- Need Handrails on both sides
 - Installed 24 42 inches
 - Full length of the ramp
 - Able to grip the handrail
 - Low Pass



77

Guttering

- ➤ Components = downspout, elbow, gutter, etc.
- > Missing components or not securely attached
- Debris limiting the drain or gutter
- Damaged components causing an impact function

30-Day Repair





79

Splash Blocks – Not Required





Heating, Ventilation and Air Condition (HVAC)

- □ 10/1 to 3/31 heat inoperable or interior temp <64 deg F UAHR Failed 24 Hrs.
- □ 10/1 to 3/131 heat working, interior temp 64 to 68 deg F UAHR Failed 30 days
- ☐ Air conditioning system or device is not operational Fail 24 Hrs.
- ☐ Unvented gas, oil, or kerosene space heater (NOT ALLOWED)— Failed 24Hrs.
- ☐ Combustion chamber cover or gas shutoff valve missing Fail 24hrs
- ☐ Heating system (permanent) or device is damaged, or missing parts Failed 30 days
- ☐ The exhaust vent is in unsafe condition Failed 24 Hrs.
- ☐ Coming area HVAC is not working between 10/1 and 3/31 Fail 30 days

81

Handrails



Inspecting Handrails

© 2024 U.S. Department of Housing and Urban Development. All rights reserved.

Design and Consent Development by CVR Associates, Inc.

HVAC

- ☐ Combustion chamber cover or gas shutoff valve missing Fail 24hrs
- ☐ Heating system (permanent) or device is damaged, or missing parts Failed 30 days
- $_{\hfill \square}$ The exhaust vent is in unsafe condition Failed 24 Hrs.
- ☐ Coming area HVAC is not working between 10/1 and 3/31 Fail 30 days
- ☐ Exhaust vent is misaligned, blocked, disconnected, or improperly connected Fail 24 Hrs.
- ☐ Exhaust vent has a negative downward slope Fail 24 Hrs.
- ☐ Exhaust vent is damaged or missing- Failed 24 Hrs.

83

Open Flames Heating Unit (U& I)


NOT ALLOWED



NOT ALLOWED







85

Infestation





Infestation






87

Infestation (U & I)

- Evidence of cockroaches, mice, rats, bedbugs, etc. Failed 30 days
- Other pests bees, wasps, bats, termites, birds, squirrels, etc. Failed − 30 days

Infestations



89

Lead-Based

- Properties built before 1978 Any peeling paint
- •No Clearance Letter (Property is free of lead)
- •A child under 6 years old (HCV Only)
- *An expecting mother (pregnant) (HCV Only)

Lead Paint Hazard Visual Assessment

Moderate Fail

- Paint deteriorated < 2sf of large sfc per room
- Small surface <10% per component

Severe Fail

- Paint deteriorated > 2sf of large sfc per room
- Paint deteriorated >10% per component

91

Leak Gas or Oil (U,I & O)



■ Natural gas, propane, or oil leak or uncapped fuel supply

☐ Failed - 24 Hrs.

Leaks (U, I & O)

Natural Gas, propane, oil leak, or uncapped fuel supply - Failed 24 Hrs.

Block Sewage System (Note: Household sewage blockage – Failed 24 Hrs.

Cleanout cap is missing or detached

Plumbing leases

Fluid leaking from the sprinkler assembly

93

Lighting (U, I & O)

- ☐ Auxiliary lighting damaged, missing, or fails to illuminate
- ☐ Light fixture is damaged, inoperable, missing, or not secure
- ☐ No permanent light fixture in the kitchen and bathroom

Lighting (U, I & O)





95

Lighting Auxiliary (I & O)

Light Damage
Light Missing
Light fails to illuminate



Lighting (I & O)





97

Minimum Electric & Lighting (U)

- At least two outlets or one outlet and light fixture.
- Rooms to evaluate living room, bedroom & kitchen
- Failed 30 Days



Light Replacement

Owners must replace a light with a light. They CANNOT cover up the spot where the light was located with a blank plate cover.



99

Litter (I & O)





Litter (I & O)





101

Litter (I & O)

- \searrow 10 or more small items of litter are present with a 10 x 10 area not designated garbage
- Any number of large items have been clearly discarded in an area not designated garbage
- > Moderate Health and Safety Present a moderate risk that will cause temporary harm, if left untreated, cause or worsen a chronic condition that may have long-term adverse health effects or physical security or safety of the resident or property.

Failed - 30 days

Mold-Like Substance (U & I)

Moderate level > 4 square inches < 1 sf in a room (U)

High Levels > 1 sf but < 9 sf in a room (U&I)

Extremely High > 9 sf in a room - 24 Hrs. (U&I)

Evaluated moisture level (U)

103

Mold Like Substance (U & I)





Mold-Like Substance



105

Wesley Cager



Parking Lots (O)

- Owned by the property
- •Pothole 4" and 1 sf +
- Ponding > 3" and 5% of the parking lot is unusable



107

Private Driveway and Roads



- Access to property blocked or impassable by cars
- Road or driveways has deep pothole and 1 sf or more

Refrigerator

Refrigerator inoperable, not cooling adequately

Refrigerator component is damaged - It impacts the functionality

No refrigerator present (Landlord providing)

109

Retaining Wall

- Retaining wall is leaning away from the fill side.
- ☐ Retaining wall is partially or completely collapsed.



Roof Assembly (O)

- Restricted flow of water from the roof drain, gutter and downspout
- •Gutter component is damage, missing and unfixed
- Roof surface has standing water
- Substrate is exposed
- . Hole in the roof not cover by a vent or screen
- . Roof assembly included vents, soft, fascia, etc.

111

Roof Failed Items





Roof/siding Failed Items





113

Sharp Edges (U, I & O)

Physical hazards with the built environment that can lacerate or puncture the skin

Sharp edges hazard injury may require emergency care

Example – broken glass, damaged tiles, or damaged handrail

Evaluated – Only recordable if within the normal path of travel.



Security Fencing/Gates

- Fences that are inspectable are the following:
 - Safety for residents
 - Prevent property damage
 - Prevent theft or injury

115

Safety





Fencing and Gates

- ☐ Hole(s) affecting 20% of the single section
- ☐ Gate latch/lock inoperable
- ☐ Failing post(s) allowing for lean or instability
- ☐ Fence must be at least 48" tall



117

Theft





Dumpster Enclosure – **No Inspectable**



HOWEVER:

We will look for tripping hazards and Sharp Edges

119

Trip Hazard

- Abrupt change in standard path
- ■3/4 inch vertical deviation
- 2-inch horizontal separation

Tripping Hazard





121

Sharp Edge

Sharp edge noted – Likely to require professional medical treatment.

Sharp Edge (U, I & O)





123

Sharp Edge (U, I & O)





Sharp Edges (U, I & O)





125

Sidewalk, Walkways, and Ramp (O)

Overgrown vegetation

Damaged or deteriorated sidewalk

Tripping hazard

Unstable Material

Blocked or impassable

Sidewalk and Walkway






127

Sidewalk and Walkway









129

Soffit/Fascia

- > Penetrating holes noted in soffit fascia or roof deck
- Damaged causing Instability

Failed Items





131

Ramp





Smoke Detector (U&I)



- ☐ Smoke alarm is not installed where required UAHR
- ☐ Smoke alarm is obstructed
- Does not produce an audio or visual alarm when tested
- □ Located in every bedroom
- ☐ Immediate Vicinity of the bedroom hallway

133

Smoke Detector (U&I)


- □ Wall-mounted—The top edge of the smoke alarm cannot be closer than 4 inches or greater than 12 inches from the ceiling.
- ☐ It must be ceiling-mounted and greater than 4 inches from the wall.
- ☐ Every level of the unit, including a finished attic
- ☐ 36 inches from any airway (Vent, window, doorway, ceiling fan, etc.)
- □ NOTE: 12/29/24 Smoke detector must be hard-wired or installed with a 10-year sealed battery smoke detector
- ☐ Failed 24 hrs.

Sprinkler Assembly (U,I&O)

- ☐ Sprinkler encased or obstructed by an object 18 inches
- ☐ Component damaged, inoperable, missing, impacts performance
- ☐ Sprinkler assembly has evidence of corrosion
- ☐ Foreign material covers 75% + of assembly or glass bulb
- ☐ Failed 24 hrs.


135

Sprinkler Assembly (U,I&O)





Sprinkler Assembly (U,I&O)



137

Stove/Range/Microwave

- The oven is not producing heat
- ❖ No burner on the cooking range or cooktop produces heat.
- Cooking range, cooktop, or oven component missing (Unsafe for use)
- Primary cooking appliance is missing
- ❖ A Microwave is damaged or Inoperable (Primary Cooking Device Only)
- ❖ A Stove Burner is Inoperable (one operable burner exists)

Fail - 30 days

Stove/Range - Hood Fan/Light

- The hood fan does not respond to the control switch
- The hood fan exhaust system has restricted airflow
- . The hood fan component is damaged or missing, including a filter
- . The hood light does not work

❖ Fail – 30 days

- NOTE: A family may choose a Microwave in place of a stove/range but all other units have microwaves only
- If there are indications that a stove or microwave was present the owner is supplying the item must place the stove/microwave in the unit

139

Wall Covering

- >1 sq ft of missing material
- Any size hole penetrating the interior
- •Covering is not "functionally adequate."
- ■10 sq ft of peeling paint on a single wall (Post-1978 building)
- 30-Day Repair





Wall Covering (Failed)



Remember:

Any size hole that penetrates the wall is a defect.

143

Water Heater (U & I)

- ☐ Pressure relief valve or discharge pipe is obstructed
- ☐ Pressure relief valve discharge piping is damaged
- ☐ Pressure relief valve has an active leak Severe
- ☐ Pressure relief valve discharge piping is missing
- ☐ Pressure relief valve terminates higher than 6" or less than 2" from the floor
- ☐ Pressure relief valve is damaged, capped, has an upward slope, or is constructed of unsuitable material


Water Heater

- □ Chimney or flue piping is blocked, misaligned, missing, or has a negative downward slope Fail 24 Hrs.
- ☐ Gas shutoff valve is damaged, missing, or not installed Fail 24 Hrs.
- □ Discharge Piping Material Allowed: Chlorinated polyvinyl chloride (CPVC) plastic pipe/tubing, Copper pipe Cross-linked polyethylene (PEX) plastic tubing Ductile iron Cross-linked polyethylene/aluminum/high-density Polyethylene (PEX-AL-HDPE) pipe Polyethylene (PEX-AL-PEX) pipe
- Galvanized steel pipe Polyethylene/aluminum/ polyethylene (PE-AL-PE) pipe Polypropylene (PP) plastic pipe or tubing Stainless steel pipe (type 304 or 316)

145


2 – 4 Inch Discharge Line





Water Heater






147

Water heater





Water Heater



NO PVC Pipe ALLOWED

149

Windows

- Each window needs at least one operable lock
 - Aftermarket locks are allowed but must be permanently installed
- Missing Screen or damage 1" or larger (SCREENS ARE REQUIRED)
- Pane is missing or damaged (crack, weather stripping)
- Lock inoperable
- Will not open to stay open (NO PROPS)
- Window will not close (Severe)
- Egress Bedroom window (no special tool to open)

Failed Window Locks





151

Structural System (U, I & O)



- ☐ Structural system exhibits signs of severe failure
- ☐ Signs of immediate collapse
- ☐ Failed 24 Hrs.

Retaining Walls (O)

- •Only inspect Retaining Walls that are a minimum of 24" tall.
- The wall must be leaning from the fill side or portion collapsed
- LFT 24 Hr



153

Structural Damage





Tenant-Owned Items

NOTE: A tenant-owned item may become an owner's issue.

155



QUESTIONS